

FHEA NO		SHUTTLE CCTV	UNIT TYC/CLA DMG NO. 2294819-506, 508/
		CHITICAL TEMS LIST	2294821-503 SHEET 1 OF 9
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
TVC/CIA does not respond to any command via the AJ panel or the uplink  IYC Al Command Detector. Sync Stripper. Clock Divider Chain. Sync Generator. 2294880-504 A2 Command Becode Logic. Command Execution Logic. Camera Jiming Logic. 2294881-501 A4 Sync/CMD Revr. 2294884-503 A5 Automatic Light Control. 2294883-505 A6 Power On/Off Switching. Input Voltage Preregulator. Butput Voltage Regulators. A7 UC-DC Converter Frimary Oscillator/Driver. 2294886-503 A3 Master Oscillator 2295527-4	(1) No lens motion, i.e., focus, zoom, or iris.  (2) Unable to change ALC or GARMA mode.  Morst Case: Loss of mission critical video.	DESIGN FEATURE  The TVC/Lens Assembly is comprised of 16 electrical subare RCA Astro designed and fabricated using standard preconstruction. The remaining three assembles, high volume and stepper motors, are vendor supplied components which purchased according to RCA Specification Control Brawin neering and reliability assurance. Specifications per establish the design, performance, test, qualification, for a pracured piece of equipment.  Parts, materials, processes, and design guidelines for specified in accordance with RCA 2295503. This documenments for selection and control of EEE parts. To the multi availability, all parts have been selected from middle availability, all parts have been selected from middle lavel, as a minimum. In addition to the overall segment Systems Division Standard Parts List. In the case microcircuits, devices are screened and lested to the Marcured under the designations of HI-REL/3NN and SMC Sinstruments Corp, respectively. Parts not included in used in the design only after a monstandard item approvement, submitted to Reliability Assurance Engineering (the specific application(s) defined in the NSIAF by NAS Morst-Case Circuit Analyses have been performed and doc designs to demonstrate that sufficient operating margin conditions. The analysis was worst case-in that the waparameters was set to limits that will drive the output A component application review and analysis was conduct stress on each piece part by the temperature extremes i qualification and piece part by the temperature extremes i qualification, an objective examination of the design was COR to verify the control of the specificat ments.	inted-circuit board type of tage power supply, oscillator, in have been specified and gs (SCOs) prepared by engitive SCO are prepared to and acceptance requirements.  the Shuttle CCIV program are t defines the program requiremanium extent, and consistent litary specifications at the lection criteria, a subset of s document and the RCA Governof the CMOS and III family of II-SID-803C equivalent and 4t5 from RCA-SSD and lexas the above documents have been all form (MSIAF) has been pre-RAE) and approved for use in A-JSC.  umented for all circuit s exist for all operating lue for each of the variable to a maximum (or minimum).  ed to verify that the applied dentified with environmental mg values identified in RCA

Command Execution Logic.  Camera Timing Logic.  2294881-501  A4 Sync/CHD Revr.  2294884-503  A5 Automatic Light Control.  2294883-505  Ab Power On/Off Switching.  Input Voltage Preregulator.  Output Voltage Regulators.  A7 OC-DC Converter Primary  Oscillator/Oriver.  2294886-503  Spacing and routing. These requirements are reiterated specifically in drawing notes to further assure compliance. Variations between the artwork master and the final product (due to irregularities of the etching process) are also controlled by drawing notes. This prevents making defective boards from good artwork, tholes which house no lead or terminal, but serve only to electrically interconnect the different board layers, contain stitch bars for mechanical support and increased reliability.  The thru holes are drilled from a drill tape thus eliminating the possibility of human error and allowing tight control over hole and annular ring concentricity, an important reliability criterion. After drilling and etching, All copper cladding is tim-lead plated per MEL-510-1495. This provides for easy and reliable suddering at the time of board assembly, even after periods of prolonged storage.	FMEA NO. 5.2.5 CRETICALITY 2/2	<u> </u>	SHUTTLE CCTV CRETECAL TEMS LIST	UNIT <u>1VT/CLA</u> DWG NO. <u>2294819-506, 508/</u> <u>2294821-503</u> SHEET <u>2</u> Of <u>9</u>
1	TVC/CLA does not respond to any contand via the A7 panel or the uplink  IVC Al Command Detector, Sync Stripper. Clock Divider Chain. Sync Generator. 2294880-504 A2 Command Decode Logic. Command Execution Logic. Camera Timing Logic. 2294881-501 A4 Sync/CMD Revr. 2294883-505 A5 Automatic Light Control. 2294883-505 A6 Power On/Off Switching. Input Voltage Preregulator. Output Voltage Regulators. A7 OC-DC Converter Primary Oscillator/Oriver. 2294886-503 AL1 Haster Oscillator	(1) No lens motion, t.e., focus, zbom, or tris.  (2) Unable to change ALC or GAMNA mode.  Norst Case: Loss of mission critical	DESIGN_FEATURE (Continued)  BARE BOARD DESIGN (AI, A4, A5, A6, A7)  The design of the associated boards AI, A4, A5, A6, A7, copper—clad epoxy glass sheets (MENA 6-10) Grade FR-4), connections are made through printed traces which run for board surfaces. Every trace terminates at an amoular resurrounds the hole in which a component lead or terminal provides a footing for the solder, ensuring good mechanical provides a footing for the solder, ensuring good mechanical spacing and routing. These requirements are reiterated notes to further assure compliance. Variations between final product (due to irregularities of the etching provides in four product (due to irregularities of the etching provides no lead or terminal, but serve only to electrically board layers, contain stitch bars for mechanical support. The thru holes are drilled from a drill tape thus eliminal human error and allowing tight control over hole and an important reliability criterion. After drilling and etchin—lead plated per MiL-STO-1495. This provides for easing the time of board assembly, even after periods of proform BOARD ASSEMBLY DESIGN (A1, A4, A5, A6, A7-A, A7-B)  All components are installed in a manner which assures making component leads are pre-timeed, allowing total wetting or are formed to provide stress relief and the bodies of la Special mounting and handling instructions are included after final assembly. The board is coated with urethane	are constructed from laminated PER Mil-P-55617A. Circuit rom point to point on the ing. The annular ring lis located. This ring ical and electrical 5540 as are trace widths, specifically in drawing the artwork master and the tess; are also controlled by rom good artwork. Holes which ly interconnect the different and increased reliability. Lating the possibility of walar ring concentricity, and thing, All copper cladding is sy and reliable suldering at aged storage.  Asximum reliability.  Asximum reliability.  Asximum reliability.  Asximum reliability.

100 miles (1862)

FNEA NO. <u>6.2.5</u>		SHUTTLE CCTV	UN17 (VC/CLA OWG NO. 2294819-506.508/
CRITICALETY 2/2	•	· · · · · · · · · · · · · · · · · · ·	SHEET 3 OF 9
FAILURE MODE AND  CAUSE  IVE/CLA does not respond to any command via the A7 panel or the uplink  IVE A1 Command Detector. Sync Stripper. Clock Divider Chain. Sync Generator. Loss	FAILURE EFFECT  (IN FRO LIEN  (1) No lens motion, i.e., facus, zoom, or iris.  (2) Unable to change ALC  or GAMMA mode.  Worst Case: Loss of mission critical  video.	SHITTLE CCTV CRITICAL STENS LIST  RATIONALE FOR ACCEPTANCE  DESIGN FEATURE (Continued)  BARE BOARD CONSTRUCTION (A2)  The boards are of "welded wire" construction. At the badistinguish it from a normal PC board except that holes generally are not connected to PC traces. Only those proposed potentials to the JCs are on PCs. An annular ris board where each power and ground pin is located. These the trace like any other component lead. Aside from this construction techniques used in PC board layout apply.  BDARD ASSEMBLY (A2)  The drilled and etched boards are populated with several weldable pins. Power and ground pins, as well as connectively pins. Power and ground pins, as well as connectively pins. Power and ground pins, as well as connectively pins. Power and ground pins, as well as connectively pins. After welding triumed away. Circuit connections are made using #30 Awaire is welded to the pin surfaces on the board backside using a machine which is tape driven, thus eliminating due to operator error. All wiring 8 circuit performance box-level installation. After successful testing, computed to the pins surfaces on the board is inserted in the box on card-edge guides, in PC boards.  BOARD PLACEMENT	SHEET 3 OF 9  SH
		The A7-A law voltage power supply board is balted in pla perimeter. four of these mounting screws also mass thro A7-B board. These two boards are mounted face-to-face, Electrical interconnections are achieved by jumper wires A7-A houses a 34-pin connector which brings in power and module.	wigh and tie down the smaller separated by the standeffs. Between the two boards. The
		The A7 modula includes these two boards as well as power kousing is bent aluminum sheet, comprised of two halves and Q4 are secured to the lower half, and wired together put in place. By mounting Q4 directly to the aluminum berformance is assured.	screwed together. The boards  . Then the upper half is
		The Al. A2. A4. A5. A6. boards are secured in the electr gold-plated beryllium copper card guides. Commections a with blind-mated connectors. Disengagement during launc	re made to the muther board

		SHUTTLE CCTV	UNIT <u>196/CLA</u> DNG NO. <u>2294819-506, 508/</u>
FMEA NO		CRITICAL TIENS LIST	2294821-503
FAILURE MODE AND	FAILURE EFFECT ON END LIEN	RATIONALE FOR ACCEP	FANCE
TVC/CLA does not respond to any command via the A7 panel or the uplink  IYC Al Command Detector. Sync Stripper. Clock Divider Chaim. Sync Generator. 2294880-504 A2 Command Execution Logic. Command Execution Logic. Camera fiming togic. 2294881-501 A4 Sync/CHD Rowr. 2294883-505 A6 Power On/Off Switching. Input Valtage Preregulator. Output Voltage Regulators. A1 OC-DC Convertor Primary Oscillator/Oriver. 2294886-503 A13 Master Oscillator 2295527-1	(1) No leas motion, i.e., focus, zoom, or iris.  (2) Unable to change ALC or GAMMA mode.  Worst Case: Loss of mission critical video.	The Al3 assembly is a temperature compensated volt (ICVCRO) that is purchased to a specification contained requirements for performance, design, test, an product assurance provisions of the document contails as the Shuttle CCIV approval of RCA and MASA-35C. Mechanical and electic confirmed by both analysis (design reviews) and CMALIFICATION IEST for Qualification fest flow, see Table 2 located as	age controlled crystal oscillator rolled drawing that establishes d qualification of the unit. The in the identical requirements for program and must receive the trical integrity of the assembly test (qualification and acceptance).
	I	I control of the cont	

02358

		REVISED 5-7-87
CRITICALITY 2/2		SHUTTLE CCTV UNIT TYC/CLA  SHUTTLE CCTV DNG NO. 2294819-506, 508/ CRITICAL ITEMS LIST 294821-503 SHEET 5 OF 9
FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	KATEUWALE FOR ACCEPTANCE
TVC/CLA does not respond to any command via the A7 panel or the uplink  IVC Al Command Detector. Sync Stripper. Clock Divider Chain. Sync Generator. 2294880-504 AZ Command Decode Logic. Command Execution Logic. Camera Timing Logic. 2294881-501 A4 Sync/CHD Revr. 2294884-503 A5 Automatic Light Control. 2294883-505 A6 Power On/Off Switching, Input Voltage Preregulator. Output Voltage Regulators. A7 DC-DC Converter Primary Uscillator/Oriver. 2294686-503 A13 Master Oscillator 2295527-1	(1) No tens mation, i.e., focus, zoom, or iris.  (2) Unable to change ALC or GAMMA mode.  Norst Case: Loss of mission critical video.	ACCEPTANCE TEST  The CCTV systems' TVC/CLA is subjected directly, without vibration isolators which might be used in their normal installation, for the following testing:  * Vibration: 2D-88Hz: 3 dB/Oct-rise from 0.0) 62/Hz 350-750 Hz: -3 dB/M Oct-slope Test Duration: 1 Hinute per Axis  Test tevel: -3 dB/M Oct-slope  Test Duration: 1 Hinute per Axis  * Thermal Vacuum: In a pressure of 1210-5 Terr, the temperature shall be as follows:  125' F: Time to stabilize equipment plus 1 hour 25' F: Time to stabilize equipment plus 1 hour 125' F: Time to stabiliz

TYC/CLA 5.2.6 CHEA NO. SHUTTLE CCTV DWG NO. 2294819-506. 508/ CRITICAL ITEMS LIST 2294821-503 SHEET 6 OF CRITICALITY 2/2 FAILURE MODE AND FAILURE EFFECT <u>RATIONALE EDR ACCEPTANCE</u> CAUSE <u>an eno Item</u> OZA INSPECTION TVC/CLA does not respond to any (1) No lens motion, i.e., command via the A7 panel or the focus, zoom, ar iris. <u>Procurement Control</u> - The TYC/CLA EEEParts and hardware items are procured from uptink approved vendors and suppliers, which meet the requirements set forth is the CCIV (2) Unable to change ALC contract and Quality Plan Work Statement (HS-2593176). Rasident DCAS personnel TVC or GAMNA mode. Al Command Detector. review all procurement documents to establish the need for GSI on selected parts (PAI 517). Sync Stripper. Worst Case: Clock Divider Chain. Loss of mission critical Sync Generator. <u>Incoming Inspection and Storage</u> - Incoming Quality inspections are made on all vi dea. 2294880-504 raceived materials and parts. Results are recorded by lot and retained in file by A2 Command Decode Logic. drawing and coetrol numbers for future reference and traceability. All fee parts Command Execution Logic. are subjected to incoming acceptance tests as called for in PAI 315 - Incoming Inspection Test Instructions. Incoming flight parts are further processed in Camera Timing Lagic. 2294881-501 accordance with RCA 1846684 - Preconditioning and Acceptance Requirements for A4 Sync/CHD Revr. Electronic Parts, with the exception that DPA and PIND testing is not performed. 2294884-503 Mechanical items are inspected per PAI 316 - Incoming Inspection Instructions for A5 Automatic Light Control. mechanical items. PAI 305 - Incoming Quality Control Inspection Instruction, and 2294883-505 PAL 612 - Procedure for Processing Incoming or Purchased Parts Designated for Flight Ab Power On/Off Switching. Use. Accepted items are delivered to Material Controlled Stores and retained Input Voltage Preregulator. under specified conditions until fabrication is required. Non-conforming materials are Output Voltage Regulators. held for Material Review Board (MRB) disposition. (PAI-307, PAI 106-531). AZ DC-BC Converter Primary Oscillator/Oriver. Board Assembly & Test - Prior to the start of TVC or CLA board assembly, all items 2294886-503 are varified to be correct by stock room personnel, as the items are accumulated to Al3 Master Oscillator form a bit. The items are verified again by the operator who assembles the kit by 2295527-1 checking against the as-built-parts-list (ABPL). DCAS Mandatory Inspection Points are designated for all printed circuit, wire wrap and welded wire boards, plus harmess connectors for soldering wiring, crimping, solder aplices and quality workmanship prior to coating of the component side of boards and sleeving of harmesses. TVC Boards Specific IVC board assembly and test instructions are provided in drawing notes, and applicable documents are called out in the Fabrication Procedure and Record (FPR-2294819) and parts list Pt2294819. These include shuttle IVC assembly agtes 2593660, Process Standard RTV-566 2280881, Process Standard - Bonding Valory Tape 2280889, Specification Soldering 2280749, Specification Name Plate Application 1960167, Specification - Crimping 2280800, Specification - Bonding and Staking 2280878. Specification - Urethame coeting 2280877, Specification - locking compound 2026116, Specification Epoxy Adhesive 2010985. Specification - Marking 2280876. Specification - Workmanship 8030035. Specification - Bonding and Staking 2280875.

REVISED 5-7-87

			WEATOR 2-1-01
FNEA ND. <u>6.2.6</u> CRITICALITY <u>2/2</u>		SHUTTLE CCTV CRETICAL IVENS LEST	UNIT FYE/ELA  DWG WO. 2294819-506 508/ 2294821-503  SHLET J OF 9
FAILURE HODE AND CAUSE	FAILURE EFFECT ON END ITEM	RATIONALE FOR ACCEPTANCE	
TVC/CLA does not respond to any command via the A7 page or the uplink  TYC Al Command Detector. Sync Stripper. Clock Divider Chain. Sync Generator. 2294880-504 A2 Command Decode Logic. Command Execution Logic. Camera Timing Logic. 2294881-501 A4 Sync/CMD Revr. 2294884-503 A5 Automatic Light Control. 2294884-505 A6 Power On/Diff Switching. Input Voltage Preregulator. Butput Voltage Regulators. A7 DC-DC Converter Primary Bscillator/Driver. 2294886-503 113 Master Dscillator 2295527-1	(1) No lens motion, i.e., focus, zoom, or iris.  (2) Unable to Ghange ALC or GAMMA mode.  Morst Case: Loss of mission critical video.	O/A INSPECTION (Continued)  IVE Assembly and Test - An open box test is performed acceptance lest per IP-AT-2294819, including vibration are specified and witnessed, traceability numbers are reare thecked prior to use. REA Quality and OCAS inspectic completion of specified FPR operations in accordance with and PAI 217. DCAS personnel witness IVC button-up and conflict and PAI 217. DCAS personnel witness IVC and an ELA have they are maked and a final acceptance test is performed vibration and thermal vacuum environments. RCA and DCAS and review the acceptance test data/results. These personnels are after all repair, rework and retest.  Preparation for Shipment - The TVC and CLA are separated fabrication and testing is complete. Each is packaged and 228074b, Process standard for Packaging and Handling documentation including assembly drawings, Parts List, A yathered and held in a documentation folder assigned spelinis folder is retained for reference. An EIDP is preparaccordance with the requirements of NS-2593176. RCA QC crating, packaging, packing, and marking, and review the accuracy.	er TP-II-2294819, and an and thermal vacuum. Torques corded and calibrated tools ons are performed at the h PAI-264, PAI-205, PAI 206 ritical torquing.  has been tested individually, per IP-AI-2294819, including personnel manitor these tests onnel also inspect for concording to CCIV tetter 8011 guidelines. All related BPL, Test Data, etc., is cifically to each assembly, and DCAS personnel witness

FHEA NO. <u>6.2.5</u> CRITICALIFY <u>2/2</u>		SHUTTLE CCTV CRIVICAL ITEHS LIST	UNIT <u>FYC/CLA</u> OWG NO. <u>2294819-506, 50B/.</u> 2294821-503 SHEET <u>B</u> OF <u>9</u>
FAILURE HODE AND CAUSE	FAILURE EFFECT ON END ITEN	RATIONALE FOR ACCEPTANCE	
IVC/CLA does not respond to any command via the A7 panel or the uplink  IVC Al Command Detector. Sync Stripper. Clock Divider Chain. Syac Generator. 2294800-504 A2 Command Decode Logic. Command Execution Logic. Camera Liming Logic. 2294881-501 A1 Sync/CMD Rowr. 2294884-503 A3 Automatic Light Control. 2294883-505 A6 Power Dn/8ff Switching. Input Voltage Preregulator. Output Voltage Regulators. A1 DC-DC Converter Primary Oscillator/Driver. 2294886-503 A13 Master Oscillator 2295527-1	(1) No lens motion, i.e., focus, zoom, or iris.  (2) Unable to change ALE or GAHMA mode.  Morst Case: Loss of mission critical video.	FAILURE MISTORY  IDR - W2644 - Leg #0462, TYC S/N F003-502  Description: Integration Testing failure	igh voltage winding of mer (sent to vendor for analysis). puc control drawing ECN CCTV  unit at KSC revealed a  pin. It is 0.035" shorter in  Ji connector. Test pins ability retention test to insure pla s not pushed out of place.

UN11 FNEA NO. 5.2.5 SHUTTLE CCTY DWG NO. 2294819-506, 508/ CRITICAL ITEMS LIST 2294621-503 CRITICALITY 2/2 SHEET BA\_ OF FAILURE HODE AND FAILURE EFFECT OH END LIEH RATIONALE FOR ACCEPIANCE. CAUSE TVC/CLA does not respond to any FAILURE HISTORY (1) No leas motion, i.e., command via the A7 panel or the focus, zoom, or iris. Cause: Incorrect wiring of shuttle craft harness, put +28Y to JI-10 and uplink RIN to JI-9. (2) Unable to change ALC TVC or GANNA mode. <u>Corrective Action</u>: Wiring of shuttle Marmess to be repaired by responsible Al Command Detector. organization. Failure analysis performed and corrective action taken on IVC Sync Stripper. Worst Case: Clack Divider Chain. 5/N 048. A6 beard-failure analysis indicated the following parts are to be Loss of mission critical changed. Q1, Q3, Q12, CR3, CR6, and R5) were replaced. Sync Generator. widen. 22948<del>80</del>-504 IDR - H8024 - Log #0530 - TVC 5/N 007-502 A2 Command Decode Logic. Command Execution Logic. Description: Acceptance lest failure Camera Timing Logic. Hox Level 2294681-561 Thermal Vac - Hot Environment. A4 Sunc/CMD Revr. 2294B84-5D3 IVC drawing excessive current, >1.5A. failure occurred at +1250f. AS Automatic Light Control. 2294883~505 <u>Cause</u>: Capacitor C10 on the A6 board was found to be shorted. A large quantity of solder flowed inside from sleeve thro header. Ab Power On/Off Switching. Input Voltage Preregulator. Output Voltage Regulators. <u>Corrective Action</u>: Capacitor C10 removed & replaced, (random part failure), A7 OC-OC Converter Primary Oscillator/Oriver. TDR - N6823 - Lag #558 - TVC S/N 012-502 Y1771 - Log #568 - TVC S/N 009-502 2294886-503 Al3 Haster Oscillator Y1771 - Lag #568 - TVC S/N 002-502 2295527-1 Y1771 - Lag #568 - TVC 5/N 009-502 Y1770 - Log #567 - TVC \$/N D14-502 Y1770 - Log #567 - IVC S/N 010-502 Y1770 - Log #566 - TVC S/N 017-502 H1729 - Log #578 - TVC \$/N 020-502 Description: Flight Failure, Spacecraft Level RMS TV Comera circuit breaker popped open during flight mission SIS-3. <u>Cause:</u> Camera low voltage supply has erratic syncronisation mode at low temperature. <u>Corrective Action</u>: All flight cameras were returned under CCA35 for rework and retest to CCN C-1881. ECN (C-1881) to the law voltage power supplies eliminates the erratic syncromization problem. TVC group part no. has been changed from 2294819-502 to 504 to denote cameras that contain low voltage power supply medification.

\_TVC/CLA dN1T OWG NO. \_\_2294819-506. 508/ SHUTTLE CCTV FHEA NO. <u>5.2.</u>5 2294821-503 CRITICAL LIENS LIST 6B CRITICALITY 2/2 FAILURE EFFECT FAILURE MODE AND RATIONALE FOR ACCEPTANCE CAUSE ON END ITEM FAILURE HISTORY (1) No lens motion, i.e., FVC/CLA does not respond to any command via the A7 panel or the facus, 2000, or iris. 1DR - Y1773 - Log #0570 - TVC \$/N 008-502 up] ink (2) Unable to change ALC Description: Flight Failure or BAMMA mode. Spacecraft Level (STS-3) Al Command Detector. Sync Stripper. Worst Case: TVC not synchronized for approximately 38 minutes. Clack Divider Chain. Loss of mission critical This problem occured at cold temperature. Sync Generator. video. Synchronization was regained at 20C. 2294880-504 A2 Command Decode Logic. Cause: Loss of phase lock due to thermal assymetry of the 3.58 MHz Phase Command Execution Logic. detector. Camera Timing Logic. 2294881-501 Corrective Action: CCA 39 has been issued directing RCA to incorporate the A4 Sync/EMD Reve. heater and sync modifications (ECN CCT 838) to all flight camera's. TVC 008 2294884-503 was modified accordingly. IVC group number has been updated from group 502 to 506. AS Automatic light Control. 2294883-505 TOR - Y1779 - Log #576 - TVC S/N 014-502 AG Power On/Off Switching. laput Voltage Preregulator. Description: Flight Failure (STS-3) Output Voltage Regulators. Spacecraft Level A7 DC-bC Converter Primary Oscillator/Oriver. TDR was opened to follow relay Ki - contacts 5 and 8 failure on ass'y 2294886-503 2294885-501 S/N FOIB. Al3 Haster Oscillator 2295527-1 Cause: TVC low voltage power supply has erratic synchronization at low temperature. Relay fallure result of excessively high current through contacts 5 and 6 during reset command. Corrective Action: Removed and replaced K1 on the A6 board. low voltage power supply was reworked to kin-CIBB). Refer to 108 M6823 for complete history of erratic synchronization problem. TOR - W6859 - Log #0695 - TVC S/N 024-506 Description: Pre-Launch Test Failure Bax Level Ambient Environment Automatic Iris goes from open to close. <u>fause</u>: Problem could not be duplicated after extensive testing. Corrective Action: Name - unil returned to KSC.

5-114B

CON. DAIP

UMET ... TVC/CLA DWG NO. 2294819-506, 508/ SHUTTLE CCTV FMEA NO. <u>5.2.5</u> 2294821**-50**3 CRITICAL ITEMS LIST <u>8C</u> OF <u>9</u> CRITICALITY \_ 2/2 FAILURE HODE AND FAILURE EFFECT RATIONALE FOR ACCEPTANCE ON END ITEM CAUSE TVC/CLA does not respond to any (1) He lens motion, 1.e., FAILURE HISTORY facus, zoom, ar iris. command via the A7 page1 or the FDR - W6870 - Log #0722 - TVC S/N 028-506 uplink (2) Mable to change ALC or GAMMA mode. Description: Acceptance Test failure Ambient Eavironment Al Command Detector. Box Level Test Sunc Stripper. Worst Case: Clock Divider Chain. Approximately 47 seconds after initial turn on, the iris close command would be loss of mission critical Sync Generator. generated by TVC. vi de o . 2294880-5**0**4 A2 Command Decode Lagic. Cause: Internal short in the high voltage power supply (S/N 2046), which Command Execution Logic. generated spikes on the POR Line. Camera Timing Logic. 2294881-501 Corrective Action: M.V.P.S. removed from IVC and new H.V.P.S. installed. A1 Sync/CMO Acvr. Tests indicated problem solved. Power supply returned to vendor for Evaluation. 2294884-503 Refer to TDR W1735, Log #723. A5 Automatic Light Control. The problem was attributed to improper lead dress of high voltage terminal. 2294863-505 These leads have been rerouted and extra insulation added at the HV terminal A6 Power On/Off Switching. for all new built woits. Input Voltage Preregulator. Output Voltage Regulators. TDR - H1760 - Log #0838 - TVC S/N 026-506 A? DC-DC Converter Primary Oscillator/Oriver. Description: Flight Failure, Spacecraft Level 2294886-503 STS-B 13 Haster Oscillator During the flight operations, one time when crew turned camera on they had no 2295527-1 control of ALC and Gamma functions. Problem resolved itself by recycling power. Cause: After numerous operators, the reported condition was duplicated on test set. After initial term on, camera would not except ALC, and Gamma commands. It was found that the output of U33 Pin 6 CMD F.F. reset on A2 board was set. in a high state. This should normally have been reset low by either "POR" or bit count 86 pulses, after initial power turn-on. Suspect devices A2 - U26, U66, U67, and U68. <u>Corrective Action:</u> Removed and replaced the following parts on the A2 Board 026, 066, 067, and 068. Lab analysis did not indicated any defect with removed parts. Problem has not recurred after new parts were installed.

FMEA NO. 5.2.5  CRITICALITY 2/2  FAILURE NOOE AND	FAILURE EFFECT	SMUTTLE ECTV CRITICAL ITEMS LIST	UHIT <u> </u>
CAUSE  IVC/CLA does not respond to any command wis the A7 panel or the splink  IVC  I) Command Delector. Sync Stripper. Clock Divider Chaim. Sync Generator. 2294880-504  I) Command Decode Logic. Command Emecution Logic. Camera Timing Logic. 2294881-569  I) Sync/CDD Revr. 2294884-503  I) Automatic Light Control. 2294883-565  I) Power Un/Off Switching, Input Voltage Preregulator. Gulput Voltage Regulators. I] DC-DC Converter Primary I) Scillator/Driver. 2294886-503  I) Master Oscillator 2295527-I	ON END ITEM  (1) No lens motion, 1.8., facus, zoom, or iris.  (2) Unable to change ALC or SAMMA mode.  Worst Case: Loss of mission critical video.	FAILURE HISTORY  TOR - A3939 - Log #0954 - TVC 5/N 031-506  Description: Flight Failure, Spacecraft Level STS-14  Problem report PV6-004037 No video output  Cause: Defective Relay K-1 on the A6 Board.  Corrective Action: Cause due to a foreign conduct ledged between relay leads and board F.C. traces. assurance lab for analysis, report #A3909. Numero found, none of which were critical.  IDM - 8-3521 - Log #1165 - TVC S/N 038-508  Description: Acceptance Test Failure  Box Level  Thermal Vac - Not Environment  Excessive supply current, lost all DLR/camera light  Cause: Shorted capacitor C14 on A6 board.  Corrective Action: C14 removed and replaced with lab could mat find a cause for shorted cap. (Report Considered random failure.	tive particle temporarily Relay K-1 sent to product bus discrepancies were was and output video information.
	I		

	· ·	REWISED 5-7-8
FMEA NO. 5.2.6  ERITICALITY 2/2  FAILURE HODE AND CAUSE  IVC/CLA does not respond to any command via the A7 panel or the uplink  IVC AI Command Detector. Sync Stripper. Clock Divider Chain. Sync Generator. 2294880-504 A2 Command Decode Logic. Command Decode Logic. Command Decode Logic. 2294881-503 A4 Sync/CHO Revr. 2294884-503 A5 Autom: Light Control. 229488	FAILURE EFFECT  DN END TIEM  (1) Mo lens motion, i.e., focus, zoom, or fris-  (2) Unable to change ALC or GAMMA mode;  Worst Case; Loss of mission critical video.	SMATTLE CCTV CRITICAL ITEMS LIST  SHEET 176.76LA SUBJ. 2294819-566. 50BJ. 2294821-503 SHEET 9 W 9  RATIONALE FOR ACCEPTANCE  OPERATIONAL EFFECTS  Loss of video. Possible luss of major mission objectives due to loss of RMS cameras or other required cameras.  CREN ACTIONS  If possible, continue RMS operations using alternative visual cues.  CREW HARINING  Grew should be trained to use possible alternatives to CCTV.  MISSION CONSTRAINI  Where possible, procedures should be designed so they can be accomplished without CCTV.
		j